

Stepping and repeating items

For jobs that are missing a CAD file, you can create one using the dieline separation from the 1-up artwork, if it exists. CAD Correct can import an EPS file of the die-line separation, identify the die lines, step it to create the die layout, and produce a CF2 file for Pandora software.

To step and repeat an item:

1. Open an EPS file of a single die station.
For more information about opening files, see [Opening files](#).
2. In the **Input file** pane, in the **Current Item** list, select **Die_0**.
3. Select the **S&R** tab.
4. Define the step-and-repeat settings.
For more information about step-and-repeat settings, see [S&R tab](#).
To step and repeat more than one item, step the first item, then add another die (a single EPS die station). For more information about adding dies, see [Loading multiple dies into a layout](#).
5. Click **OK**.