

Adding lines to an item

The CAD file may contain an item with incomplete perimeter lines. CAD Correct lets you add lines to complete the shape of the item. CAD Correct follows the direction indicated by the pointer tool, and all added lines must be created in this direction.

To add lines to an item:

1. In the **Input file** pane, in the **Current Item** list, select the item.
2. Select the **Line** tab.
3. Click **Editing**.
Editing changes to **Stop Editing** and a green circle with an "X" in it appears.
4. In the **Preview** pane, click the location where you want the line to begin, and drag to the location where you want the line to end.
5. Click **Stop Editing**.