

Loading multiple dies into a layout

You cannot open multiple input files in CAD Correct, but you can add multiple dies to a layout.

To load multiple dies:

1. From the **File** menu, select **Add Die**.
2. Select the item you want to add, then click **Open**.
The added items appear in the **Current Item** list and are numbered sequentially.