

Setting the line appearance for all dies

You can show all lines in the file, select individual line types, or choose to show only die station lines.

All lines will appear with the name they were assigned in the original CAD file, with the following exceptions:

- Cut
- Crease
- Perforation
- Score

If you find that more die stations are appearing than you expected, modify your die file to ungroup all die stations or convert all die stations to cut lines.

1. Select **Pandora > Preferences** (Macintosh) or **Edit > Preferences** (Windows).
2. In **Preferences**, select the **Die Settings** tab.
3. In the **Import Die Filters** area of the **Line Types to Exclude** section, type the names or numbers of the line type(s) you want to exclude in the **CFF2** or **DDES2** box. Use commas to separate the numbers—for example 11,14,17.
4. Click **OK**.